

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION III 841 Chestaut Building

841 Chestnut Building Philadelphia, Pennsylvania 19107

Office of Superfund Robert Thomson, P.E. Mail Code 3HW50

Direct Dial (215) 597-1110 FAX (215) 597-9890

Date: February 6, 1996

Mr. Richard N. Stryker

Atlantic Division, Naval Facilities Engineering Command

Environmental Quality Division

Code: 1822

Building N 26, Room 54 1510 Gilbert Street

Norfolk, Va 23511-2699

Re:

Naval Weapons Station, Yorktown, Va.

Site 12

Review of the Navy's 1/9/1996 Response to EPA's 11/9/1995 Review comments

Dear Mr. Stryker:

The U.S. Environmental Protection Agency (EPA) has reviewed the Navy's January 9, 1996 response letter to EPA's November 9, 1995 review letter concerning the draft *Remedial Investigation* for Site 12, located at the Naval Weapons Station-Yorktown, and we offer the following comments as outlined below:

- 1. EPA recommends that an attempt to measure contaminant uptake in aquatic organisms, via tissue sampling, be undertaken at Site 12.
- 2. Lead should be retained as a contaminant of ecological concern for sediment at Site 12.
- 3. Please reference Ms. J. Dinan of the USEPA, including address and telephone number. For future reference, please coordinate toxicological issues related to the Naval Weapons Station-Yorktown with Nancy Jafolla.

If you have any questions regarding the above, please feel free to call me at (215) 597-1110,

Sincerely,

Robert Thomson, PE

Superfund Federal Facilities (3HW50)

cc:

Steve Mihalko (VDEQ, Richmond) Jeff Harlow (WPNSTA, 09E) Bob Davis (USEPA, 3HW13) Nancy Jafolla (USEPA, 3HW13) Bruce Rundell (USEPA, 3HW13)